

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 25-07-2022 to 24-08-2022
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): SUNCOR / EMERA
 Dive Number(s): #3 Dive (50 to 53) / #23 Dive 1 to 23
 Dive Location: CABOT STRAIT
 Support Vessel/Installation: AHNS HORIZON ARCTIC
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 72

Total Time (this tour):

Hrs	18	Mins
Hrs		Mins

 Cumulative Pilot Hours (total): 1422
 Type of Operation: 440
 MOORING CHAIN INSTALLATION
 SURVEY

Sensors/Manipulators used:

T4 - RIGMASTER - SSS - MBES - INNOVA MUX

Name of Supervisor in Charge (and Company):

Robert Murphy

Horizon Arctic
 St. John's, NL
 IMO 9732838
 GT 8143 KW20640

Signature Verifier:

Date:

Signature Project Manager:

Date:

22-08-24

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 16-09-2022 to 11-11-2022
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #10 (01 to 10) / #27 (01 to 27)
 Dive Location: EAST ITALY/GREECE WEST ITALY
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs	63	Mins
Hrs		Mins

 Cumulative Pilot Hours (total): 1485
 Type of Operation: 440
 GEOPHYSICAL SURVEY

Sensors/Manipulators used:

MUX - SUB BOTTOM - TSS - MBES - T4 - ATLAS

Name of Supervisor in Charge (and Company):

Alexis Shaw

Signature Verifier:

Date:

11/11/22

Signature Project Manager:

NG WORKER
 IMO 9533244

Date:

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 05-12-2022 to 29-12-2022
 Name of Contractor: BOUBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 20 (57 to 77)
 Dive Location: WEST ITALY
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs
39
Hrs
1524
440

Mins
Mins

Cumulative Pilot Hours (total):

Type of Operation:

GEOPHYSICAL SURVEY

Sensors/Manipulators used:

MUX - TSS - SUB BOTTOM - SMART SEARCH - MBES


Name of Supervisor in Charge (and Company):

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 26-01-23 to 23-02-23
 Name of Contractor: BOUBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 22 (102 to 124)
 Dive Location: WEST ITALY
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs
33
Hrs
1557
440

Mins
Mins

Cumulative Pilot Hours (total):

Type of Operation:

GEOPHYSICAL SURVEY

Sensors/Manipulators used:

MUX - TSS - SMART SEARCH - MBES - SSS - SUB BOTTOM
 T4 - ATLAS

Name of Supervisor in Charge (and Company):


DAN STEPHENS

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 23-03-2023 to 26-04-2023
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 27 (Dive 151 to 177)
 Dive Location: OFF SICILY ITALY
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs	43	Mins
Hrs		Mins



 Cumulative Pilot Hours (total):

Hrs	1600	Mins
Hrs	440	Mins

 Type of Operation: GEOPHYSICAL SURVEY
 FREELY TRENCH

Sensors/Manipulators used:
 MUX - TSS - SMART SEARCH - MBES - SUB BOTTOM PROFILE - T4 - ATLAS

Name of Supervisor in Charge (and Company):
 DIRK STEPHENS - OFFSHORE MANAGER NGW

Signature Verifier:  Date: 24/4/23
 Signature Project Manager:  Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 18-05-2023 to 16-06-2023
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 16 (Dive 01 to 16)
 Dive Location: OFF ITALY
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs	35	Mins
Hrs		Mins



 Cumulative Pilot Hours (total):


Hrs	1635	Mins
Hrs	440	Mins

 Type of Operation: GEOPHYSICAL SURVEY AND UXO OPERATIONS
 FREELY TRENCH

Sensors/Manipulators used:
 MUX - TSS - SMART SEARCH - MBES - ZIP PUMP - ATLAS - T4 - BOOMS AND

Name of Supervisor in Charge (and Company):

Signature Verifier:  Date:
 Signature Project Manager:  Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 28.06.2023 to 27.07.2023
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): HORIZON MARITIME / EXXON MOBIL
 Dive Number(s): #5 (Dive 1 to 5) #1 (Dive 1)
 Dive Location: (GALE) NFLD - CANADA - NOVA SCOTIA
 Support Vessel/Installation: AHVS HORIZON ARCTIC (ALMA)
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 72

Total Time (this tour):

Hrs
/

Mins
/

Cumulative Pilot Hours (total):

Hrs
1635

Mins

FREE FLY
TRENCH

Type of Operation:

440

ANCHORS/CHAINS INSTALLATION AND SURVEY
 BUBBLE WATCH

Sensors/Manipulators used:

T4 / RIGMASTER / SONAR / BLUE VIEW
SEATING

Name of Supervisor in Charge (and Company):

Signature Verifier:

Date: 27.07.2023

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 01/09/23 to 29/09/23
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): HORIZON MARITIME / EXXON MOBIL
 Dive Number(s): #8 (Dive 1 to 8) - #15 (Dive 1 to 15) - #1 (Dive 1)
 Dive Location: NFLD - CANADA GALE/PERSEPHONE NOVA SCOTIA
 Support Vessel/Installation: AHVS HORIZON ARCTIC (ALMA)
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 72

Total Time (this tour):

Hrs
20

Mins
/

Cumulative Pilot Hours (total):

Hrs
1655

Mins

FREE FLY
TRENCH

Type of Operation:

440

ANCHORS/CHAINS RECOVERY - GRID SURVEY (DEEP DIVE 3003m)
 BUBBLE WATCH

Sensors/Manipulators used:

T4 / RIGMASTER / BLUE VIEW / SONAR / LASERS

Name of Supervisor in Charge (and Company):

Horizon Arctic
 CHA2033
 St John's, NL
 Kongsberg KPOB DP21

Signature Verifier:

Date:

Signature Project Manager:

Date: 29-09-2023

IMCA ROV Personnel Logbook Record of Work Experience

13-11-2023 to 22-11-2023
SYSTEM MOBILIZATION HD23 to IEVOLI COBALT

Note: Use one page per tour of duty unless a separate dive record is required



Tour Date/Date of Dive: 03-12-2023 to 29-12-2023
Name of Contractor: BOURBON OFFSHORE DNT
Client Name(s): NEXT GEOSOLUTIONS
Dive Number(s): #29 (Dive 1 to 29)
Dive Location: OFF SICILY ITALY
Support Vessel/Installation: PSV IEVOLI COBALT
Position During Tour(s): ROV SUPERVISOR
Type of ROVs: Manufacturer: SCHILLING
Model: HD
Unit Number: 23

Total Time (this tour):

Hrs	Mins
5	00
Hrs	Mins
1660	

Cumulative Pilot Hours (total):

440

Hrs	Mins
00	00
Hrs	Mins

FREE FLY
TRENCH

Type of Operation:

ATLAS GEOPHYSICAL SURVEY

Sensors/Manipulators used:

ATLAS T4, PODS, GRABBER, SRP, SSS, MBES GEMINI - LASERS

Name of Supervisor in Charge (and Company):

[Signature]

DIRE SUTER

Signature Verifier:

[Signature]



Date:


29/12/23

Signature Project Manager:

*

Date:

IMCA ROV Personnel Logbook Record of Work Experience



Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 22-01-24 to 27-01-24 / 27-01-24 to 25-02-24
Name of Contractor: BOURBON OFFSHORE DNT
Client Name(s): NEXT GEOSOLUTIONS
Dive Number(s): #20 N/A
Dive Location: N/A
Support Vessel/Installation: IEVOLI IVORY / NG WORKER
Position During Tour(s): ROV SUPERVISOR
Type of ROVs: Manufacturer: SCHILLING
Model: HA
Unit Number: 01 / 28

Total Time (this tour):

Hrs	Mins
00	00
Hrs	Mins
1660	

Cumulative Pilot Hours (total):

440

Hrs	Mins
00	00
Hrs	Mins

FREE FLY
TRENCH

Type of Operation:

1 WEEK ON IVORY - AUDIT ON SYSTEM - HOSES REPLACEMENT - ROUTINE MAINTENANCE
4 WEEK ON WORKER - HOSES/ROTOR REPLACEMENT AND OTHERS IMPROVEMENT ON O&M


Sensors/Manipulators used:

Name of Supervisor in Charge (and Company):

JALERO TUCCI

Signature Verifier:

A. SHAN



Date:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 17-03-2024 to 15-04-2024
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 19 (Dive 01 to 19)
 Dive Location: ITALY OFF TRAPANI SICILY
 Support Vessel/Installation: IEVOLI COBALT
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 23

Total Time (this tour):

Hrs
36
Hrs
1656

Mins
00
Mins

Cumulative Pilot Hours (total):

440

FREE FLY
TRENCHER

Type of Operation:

SYSTEM MAINTENANCE

PIPELINE EXTERNAL INSPECTION

Sensors/Manipulators used:

T4 ATLAS BOOM ARMS - MBES - SSS - PHINS - GEMINI - MUX - TSS - SUB BOTTOM

Name of Supervisor in Charge (and Company):


1820 MICHAEL CAPTAIN

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 18-04-24 to 04-05-24
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): HORIZON MARITIME
 Dive Number(s): # 12 (Dive 20 to 32)
 Dive Location: OFF CANADA WHITE ROSE FIELD
 Support Vessel/Installation: AHV'S HORIZON ARCTIC
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 72

Total Time (this tour):

Hrs
60
Hrs
1756

440

Mins
Mins

FREE FLY
TRENCHER

Type of Operation:

MOORING CHAINS REPLACEMENT

Sensors/Manipulators used:

T4 RIGMASTER - GEMINI - MINI IPS

Name of Supervisor in Charge (and Company):


MIKE CHILDS

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 14-07-24 to 07-08-24
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): # 16 (Dive 50 to 66)
 Dive Location: SPAIN BILBAO OFFSHORE
 Support Vessel/Installation: MPSV NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HA
 Unit Number: 28

Total Time (this tour):

Hrs
5
Hrs
1761
440

Mins
Mins

FREE FLY
TRENCH

Cumulative Pilot Hours (total):

Type of Operation:

GEOPHYSICAL SURVEY - THRUSTER AND JOINT INSPECTION

Sensors/Manipulators used:

MUX - SBP MBES - SSS - LASERS - SVX - TSS

Name of Supervisor in Charge (and Company):


Signature Verifier:

[Signature]

Date: 07/08/2024

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive:
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): HORIZON MARITIME - EXXON
 Dive Number(s): # 4 (Dive 17 to 21)
 Dive Location: CANADA PERSEPHONE FIELD
 Support Vessel/Installation: AHVS HORIZON ARCTIC
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HA
 Unit Number: 72

Total Time (this tour):

Hrs
13
Hrs
1774
440

Mins
Mins

FREE FLY
TRENCH

Cumulative Pilot Hours (total):

Type of Operation:

BEACONS RECOVERY - DEPOSITION POLES RECOVERY
 SURVEY GRID WITH BIOLOGIST ANALYSIS

Sensors/Manipulators used:

TL RIGMASTER

Name of Supervisor in Charge (and Company):


BRAD FORTY

Signature Verifier:

[Signature]

Signature Project Manager:

Date:



Horizon Arctic
CHA2033
St John's, NL

Kongsberg KPOS DP21

11-Sept 2024

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 16-09-24 to 19-09-24
 Name of Contractor: BOORBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #3 (Dive 1 to 3)
 Dive Location: OFF SPAIN
 Support Vessel/Installation: IEVOLI COBALT
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 23

Total Time (this tour):

Hrs
3
Hrs
177
440

Mins
00
Mins

FREE FLY
TRENCH

Cumulative Pilot Hours (total):

Type of Operation:

SEARCH OPERATIONS

Sensors/Manipulators used:

T4 ATLAS - GEMINI

Name of Supervisor in Charge (and Company):

SM NICHOLS

Signature Verifier:

Signature Project Manager:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 30-09-24 to 16-11-24
 Name of Contractor: BOORBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #123 (Dive 1 to 123)
 Dive Location: OFF ITALY
 Support Vessel/Installation: IEVOLI COBALT
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 23

Total Time (this tour):

Hrs
18
Hrs
1785

Mins
50
Mins

FREE FLY
TRENCH

Cumulative Pilot Hours (total):

Type of Operation:

GEO-TECHNICAL AND GEOPHYSICAL SURVEY

Sensors/Manipulators used:

TSS RADIOETER BOOMS MIX PHMS GEMINI LASERS 1785 SSS SSB

Name of Supervisor in Charge (and Company):

ANDREA GUARINO

Signature Verifier:

Signature Project Manager:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 06/01/2025 to 27/01/2025
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #2 (Dive 1 and 2)
 Dive Location: OFF ITALY - SICILY
 Support Vessel/Installation: IEVOLI COBALT
 Position During Tour(s): ROV SUPERVISOR - SUPERINTENDANT
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 23

Total Time (this tour):

Hrs
4
Hrs
1799

Mins
00
Mins

Cumulative Pilot Hours (total):

440

FREE FLY
TRENCH

Type of Operation:

LARS CHANGE OUT AND CONTAINERS - ROV PENNINS ONBOARD -
 DECK LAYOUT - ELECTRIC AND HYDRAULIC CONNECTIONS - SENSORS
 INTERFACING -

Sensors/Manipulators used:

Name of Supervisor in Charge (and Company):

GIUSEPPE COPPOLA VESSEL SUPT.

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 28/01/2025 to 17/02/2025
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #2 (Dive 1 and 2)
 Dive Location: OFF HOLLAND
 Support Vessel/Installation: IEVOLI AMBER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 98

Total Time (this tour):

Hrs
4
Hrs
1803

440

Mins
00
Mins

FREE FLY
TRENCH

Type of Operation:

LARS AND ROV SYSTEM MOBILIZATION - DECK LAYOUT
 ELECTRIC AND HYDRAULIC CONNECTIONS - SENSOR INTERFACING -

Sensors/Manipulators used:

ROV INS - DREDGER 6" - SVX

Name of Supervisor in Charge (and Company):

GIUSEPPE COPPOLA VESSEL SUPT.

Signature Verifier:

Date:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 17/03/2025 to 28/03/2025
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): BOURBON OFFSHORE DNT WAREHOUSE
 Dive Number(s): NONE
 Dive Location: ITALY - RAVENNA
 Support Vessel/Installation: WARE HOUSE
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 09

Total Time (this tour):

Hrs
✓
Hrs
1803
440

Mins
✓
Mins

Cumulative Pilot Hours (total):

Type of Operation:

MAINTENANCE AND TROUBLESHOOT ON SYSTEM

Sensors/Manipulators used:

Name of Supervisor in Charge (and Company):

PAOLO TULPANTI OPERATIONS MANAGER
Bourbon Offshore DNT

Signature Verifier:

Signature Project Manager:

Via V.E. Orlando, 2

48123 Ravenna

P. IVA IT02085700397

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 10/04/2025 to 29/04/2025
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #3 Dive (85 to 88)
 Dive Location: ITALY - OFF SICILY
 Support Vessel/Installation: NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs
3
Hrs
1806
440

Mins
00
Mins

Cumulative Pilot Hours (total):

Type of Operation:

USBL DEPLOYMENT AND SURVEY VERIFICATIONS
MAINTENANCE ON SYSTEM; T4, ATLAS, TNS, NODES

Sensors/Manipulators used:

MBES, SBP, SSS


Name of Supervisor in Charge (and Company):

OSANA GOBARA CHIEF

Signature Verifier:

Signature Project Manager:

Date:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 03/05/2025 to 19/05/2025
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #16 (DIVE 1 to 16)
 Dive Location: OFF ITALY
 Support Vessel/Installation: NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs	Mins
28	00
Hrs	Mins
1834	

Cumulative Pilot Hours (total):

440

FREE FLY
TRENCHER

Type of Operation:

MATTRESSES INSTALLATION - CABLE CUT - SURVEY

Sensors/Manipulators used:

38mm CUTTER, ATLAS, T4, PHINS

Name of Supervisor in Charge (and Company):

DIRK STEPHENS PARTY CHIEF

Signature Verifier:

Signature Project Manager:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 18/07/25 to 21/08/25
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #28 (DIVE 01 to 28)
 Dive Location: OFF SPAIN - BILBAO
 Support Vessel/Installation: NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs	Mins
39	
Hrs	Mins
1873	

Cumulative Pilot Hours (total):

440

FREE FLY
TRENCHER

Type of Operation:

GEOPHYSICAL SURVEY, CABLES CUT AND RELOCATION
BOULDERS REMOVAL

Sensors/Manipulators used:

T4, ATLAS, GENINI, 75mm CUTTER, GRADIENTER, TSS

Name of Supervisor in Charge (and Company):


GUARACINO GUISERRE

Signature Verifier:

Signature Project Manager:

Date: 21/08/2025

Date: 21/08/2025



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 28-08-25 to 10-10-25
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): NEXT GEOSOLUTIONS
 Dive Number(s): #13 Dive 01 to 13 #58 Dive 01 to 58
 Dive Location: SARDEGNA SICILY - MALTA
 Support Vessel/Installation: NG WORKER
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: HD
 Unit Number: 28

Total Time (this tour):

Hrs
<u>10</u>
Hrs
<u>1883</u>
<u>440</u>

Mins
Mins

FREEFLY
TRENCHER

Cumulative Pilot Hours (total):

Type of Operation:

CLASSIFIED UXO
GEOPHYSICAL SURVEY

Sensors/Manipulators used:

T4 ATLAS GRABOTETER TSS BORIS SSS

Name of Supervisor in Charge (and Company):

ROSSA GIOVANNI

Signature Verifier: [Signature] Date: 21/10/2025

Signature Project Manager: _____ Date: _____

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 23-11-25 to 10-12-25
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): BOURBON SUBSEA SERVICES
 Dive Number(s): /
 Dive Location: VESSEL ALONGSIDE IN DUBAI
 Support Vessel/Installation: NPSV TRIESTE
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: UHD
 Unit Number: 25

Total Time (this tour):

Hrs
<u>/</u>
Hrs
<u>1883</u>
<u>440</u>

Mins
Mins

FREEFLY
TRENCHER

Cumulative Pilot Hours (total):

Type of Operation:

MAINTENANCE ON THE SYSTEM

Sensors/Manipulators used:

Name of Supervisor in Charge (and Company):

BUENAVENTURA BLACH

Signature Verifier: [Signature] Date: _____

Signature Project Manager: _____ Date: _____

IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 13/01/26 to 26/03/26
 Name of Contractor: BOURBON OFFSHORE INT
 Client Name(s): BOURBON
 Dive Number(s): #6 UH37 Dive 1 to 5 UH37 Dive 1
 Dive Location: SINGAPORE - INDONESIA
 Support Vessel/Installation: BOURBON EVOLUTION 810
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: UH37 SCHILLING
 Model: UH37 UH37
 Unit Number: 37 57

Total Time (this tour):

Hrs	Mins
5	00
Hrs	Mins
1888	
440	

Cumulative Pilot Hours (total):

Type of Operation:

MOBILIZATION + SEA TRIAL SHALLOW AND DEEP WATER DIVES

Sensors/Manipulators used:

TH ROIMASTER SVX SONAR DVL BEACONS

Name of Supervisor in Charge (and Company):

Signature Verifier:

Date:

Signature Project Manager:



IMCA ROV Personnel Logbook Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 05/05/26 to 05/06/26
 Name of Contractor: BOURBON OFFSHORE INT
 Client Name(s): T7 GLOBAL VESTIGO
 Dive Number(s): #24 UH37 Dive 1 to 23 UH37 Dive 1
 Dive Location: MALAYSIA BERANTAI FIELD
 Support Vessel/Installation: BOURBON EVOLUTION 810
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: UH37
 Unit Number: 37 - 57

Total Time (this tour):

Hrs	Mins
4	00
Hrs	Mins
1892	
440	

Cumulative Pilot Hours (total):

Type of Operation:

FP SO DISCONNECTION RISERS UPRICAL - TIEBACK CHAINS
 SYSTEMS MAINTENANCE + EXTRAORDINARY MAINTENANCE ON 37 FRATE

Sensors/Manipulators used:


SVX TH ROIMASTER SONAR DVL BEACONS

Name of Supervisor in Charge (and Company):

Signature Verifier:

Date:

Signature Project Manager:



IMCA ROV Personnel Logbook

Record of Work Experience

Note: Use one page per tour of duty unless a separate dive record is required

Tour Date/Date of Dive: 14-07-26 to 27-07-26
 Name of Contractor: BOURBON OFFSHORE DNT
 Client Name(s): RELIANCE
 Dive Number(s): #9 - UHD37 (DIVE 0167) - UHD57 (DIVE 162)
 Dive Location: OFF INDIA
 Support Vessel/Installation: MPSV BOURBON EVOLUTION 810
 Position During Tour(s): ROV SUPERVISOR
 Type of ROVs: Manufacturer: SCHILLING
 Model: UHD
 Unit Number: 037 AND 057

Total Time (this tour):

Hrs
12
Hrs
1904

Mins
Mins

Cumulative Pilot Hours (total):

440

FREELY
TRENCH

Type of Operation:

VESSEL ACCEPTANCE SEATRIALS
 DEEP WATER DIVES

Sensors/Manipulators used:

RIGMASTER, T4, SEAKING SONAR, PHINS

Name of Supervisor in Charge (and Company):



Signature Verifier:

Date:

Signature Project Manager:

Date:

26.7.26

BE-810 OCM